Bugs List @ 18.12.97

Netmon : 18/12/97

Programs affected

Netmons 012-085 to 012-125

Effect on Safety

None.

Nature of fault

Display handling if using Suppress/Release Siren when no alarm is present.

Program appears to suppress siren (changes to Release Siren), but is not actually doing so.

If you leave this window and return, it has returned to Suppress Siren (indicating that the Siren is not suppressed).

However, if you remain on this window and try to Release the siren, a confusing display may result.

Information

Earlier Netmon programs allowed Siren Suppression at any time even when the siren was not active.

With revised siren handling in 011-085 upwards this is no longer possible. (See Siren Suppression data sheet.) The ability to suppress the siren when it is not operating has real no practical benefit and can produce confusing results, and has therefore been removed.

The slightly confusing result on the display is a byproduct of the program revision.

Action

Future Netmon releases - bug fixed.

Minor nature of bug does not necessitate replacement.

Others

This file will be updated on an as and when basis.